

Annexure D

BUILDING SAFETY CERTIFICATE

No 260

Dated: 10-6-2024

It is certified that the existing building Nikhari International School (name of the building or premises) at Vill: Chingrawati, Phase Bus Stand Syana BSR (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2	-	-	-	-	-

The building is owned/occupied by Nikhari International School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Paran Singh (Name of Department/ Govt.) on 27-6-2024 (date of inspection) in the presence of Sh. Devesh Singh, Dhal (name and addresses of the Manager/Secretary or his representative) and that the building/promises is fit for occupancy for running school with effect from 10-6-2024 for a period of 02 years years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 10-6-2024 at Bulandshahr by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name: Assistant Engineer

Designation : Bulandshahr

Name & Address of Department/ Office: Bulandshahr

कार्यालय सहायक अभियन्ता, ग्रामीण अभियन्त्रण विभाग, प्रखण्ड-बुलन्दशहर
पत्रांक 260/ग्रा0अ0वि0/ने0बि0को0/2024-25/दिनांक 10-06-2024

प्रमाण-पत्र

प्रमाणित किया जाता है कि निरंजन इण्टरनेशनल स्कूल, ग्राम चिंगरावठी, भर्मा बस स्टैण्ड, स्याना बुलन्दशहर का निरीक्षण अधोहस्ताक्षरी, के द्वारा दिनांक 07.06.2024 को किया गया।

भवन में बेसमेन्ट की संख्या शून्य है। भवन में दो तल है। भवन में सभी मूलभूत सुविधायें उपलब्ध है।

भवन का नेशनल बिल्डिंग कोड प्रमाण पत्र इस शर्त के साथ दिया जा रहा है कि भवन में सभी मनकों का अनुपालन किया जाये तथा भवन के इस प्रमाण पत्र का नवीनीकरण निर्धारित समयवधि के अन्तर्गत पुनः कराया जाये। भवन में कोई भी परिवर्तन बिना किसी सक्षम स्तर से अनुमति के न किया जाये। स्कूल के भवन निर्माण कार्य की गुणवत्ता की पूर्ण जिम्मेदारी आपकी/स्वामी की होगी।

भवन नेशनल बिल्डिंग कोड 2005 में प्राविधानित सुरक्षा मानकों के अनुसार निर्मित होने के कारण भूकम्प रोधी निर्मित है।

(पूरन सिंह)

सहायक अभियन्ता
ग्रामीण अभियन्त्रण विभाग,
बुलन्दशहर।

पत्रांक एवं दिनांक उपरोक्तानुसार

प्रतिलिपि:- मैनेजर/प्रबन्धक निरंजन इण्टरनेशनल स्कूल, ग्राम चिंगरावठी, भर्मा बस स्टैण्ड, स्याना बुलन्दशहर को उनके प्रार्थना पत्र के क्रम में सूचनार्थ।

सहायक अभियन्ता
ग्रामीण अभियन्त्रण विभाग,
प्रखण्ड-बुलन्दशहर।